

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	Alkalinity (mg/L)	Chloride (mg/L)	Chloride (SAC 942) (mg/L)	Chloride (SAC 160) (mg/L)	Color (TP/C)	Conductivity (µs/cm)	DO	GLYCL	Hardness (mg/L)
Primary Maximum Contaminant Levels	a																
Secondary Maximum Contaminant Levels	b									250	250	250	15				
Recommended Action Levels	c																
			Well				CABOT	5/13/2008		<2.00							
			Well				CABOT	11/05/2008		2.06							
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009									
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009		5.38				367	5.25		
			Well				DEP	5/13/2010	141.4	3.3				274			117
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	3/13/2010		14.6				353	8.19		
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010		11.8				276	4.83		
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010									
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010									
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010		4.02				213	5.22		
			Well				DEP	5/27/2010	136	3.2				267			78
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010		4.04				237	2.85		
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010		2.08				217	7.08		
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010		3.17				220	6.76		
			Well														
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010		3.76				267	7.33		
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010		2.44				230	5.81		
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010		<2.00				212	6.31		
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010		2.11				223	6.2		
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010		2.66				234	6.46		
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010		2.18				248	4.19		
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010		2.56				194	7.72		
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010		3.33				189	7.83		
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010		2.34				251	6.94		
AFTER FILTER			Well			Post-Treatment	CABOT	08/06/2010						199	7.55		
			Well				DEP	8/11/2010	117.6	1.5							89
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010									
			Well				DEP	8/18/2010	117.8	1.2				231			101
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010		3.11				207	6.7		
			Well				DEP	8/24/2010	117.4	1.3							96
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010		2.49				252	6.2		
			Well				DEP	8/31/2010	131.2	9.4				316			122
			Well				DEP	9/2/2010	115.2	1.4				241			91
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/2/2010		2.84				213	6.8		
			Well				DEP	9/9/2010	116.4	1.4				238			92
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010		3.04				190	4.75		
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010						4.2			
			Well				DEP	9/30/2010	127.2		2.4	2.18	<5	257		NON DETECT	72
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010									
			Well				DEP	10/14/2010	139	3.2				292			56
			Well				DEP	10/28/2010	126.8	3				269			64
			Well				DEP	11/2/2010	145.8	4.1				264			43
			Well				DEP	11/9/2010	145	4.2				295			41
			Well				DEP	11/22/2010	144.8	4.5				303			41
			Well				DEP	12/2/2010	135.8	3.7				286			62
			Well				DEP	12/7/2010	120	1.9				252			77
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010						241	5.54		
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011						238	5.77		
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011						183	7.91		
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011						186	8.9		
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/17/2011						245	12.91		
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011						190	8.01		
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011						193	4.95		
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011						250	6.96		
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011						211	5.49		11/1/2011 2:28 PM

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011							210	6.06		
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011							195	6.67		
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011							221	9.16		
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011							160	3.67		
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011							278	1.81		
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011							232	2.34		
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011							156	3.25		
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011							138	2.71		
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011							130	6.23		

Notes:

a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)

b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.

c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	MBAS (mg/L)	Nitrate (mg/L)	Nitrite (mg/L)	ORP (mV)	pH (pH units)	pH (SAC 942) (pH units)	pH (SAC 160) (pH units)	Sulfate (mg/L)	Sulfide (mg/L)	TDS (mg/L)	TDS (SAC 942) (mg/L)
Primary Maximum Contaminant Levels	a									10	1								
Secondary Maximum Contaminant Levels	b								0.5				6.5-8.5	6.5-8.5	6.5-8.5	250		500	500
Recommended Action Levels	c																		
			Well				CABOT	5/13/2008	<0.050				6.7				<0.05	135	
			Well				CABOT	11/05/2008	<0.020				8.35				<1	213	
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009											
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009	<0.080			-163.9	9.6				3	193	
			Well				DEP	5/13/2010					8.6						222
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	3/13/2010	<0.020			-25.1	9.14				<1	232	
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010	<0.020			103.8	8.65				<1	184	
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010					8.32						
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010					8.55						
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010	<0.020			167.2	7.62				<1	133	
			Well				DEP	5/27/2010					8.4					46	
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010	<0.020			123.6	7.66				<1	107	
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010	<0.020			120.2	7.54				<1	80	
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010	0.032			110.4	7.44				<1	88	
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010	<0.020			104.4	7.88				<1	127	
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010	<0.020				121.3	7.57			<1	160	
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010	<0.020			136	7.43				<1	120	
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010	<0.040			149.7	7.49				<1	163	
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010	<0.020			105.7	7.4				<1	136	
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010	<0.080			47.7	7.25				<1	150	
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010	<0.040			60.8	7.64				<1	125	
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010	<0.080			73.1	7.58				<1	115	
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010	<0.080			114	7.5				<1	125	
AFTER FILTER			Well			Post-Treatment	CABOT	08/06/2010	<0.080			175.6	7.63				<1	175	
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well				DEP	8/11/2010					6.1					138	
			Well			Post-Treatment	CABOT	8/12/2010					7.7						
			Well				DEP	8/18/2010					7.7					144	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010	<0.080			115.3	7.57				<1	180	
			Well				DEP	8/24/2010					7.6					142	
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010	<0.080			14.6	7.33				<1	140	
			Well				DEP	8/31/2010					7.6					180	
			Well				DEP	9/2/2010					8.1					134	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/3/2010	<0.080			111.6	7.29				<1	136	
			Well				DEP	9/9/2010					8.2					140	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010	<0.080			151.7	7.02				<1	144	
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010				174.2	7.47						
			Well				DEP	9/30/2010		<0.04	<0.01			8.5	8.5	7.58		188	158
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010					8.8						158
			Well				DEP	10/14/2010					8.3					156	
			Well				DEP	11/2/2010					9					198	
			Well				DEP	11/9/2010					8.9					124	
			Well				DEP	11/22/2010					9.2					170	
			Well				DEP	12/2/2010					8.6					172	
			Well				DEP	12/7/2010					8.2					138	
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010				111.1	7.94						
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011				131.6	7.57						
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011				142	7.05						
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011				86.9	7.96						
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/11/2011				182.7	7.12						
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011				129.6	7.56						
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011				121.5	8.08						
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011				172.1	7.77						
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011				72.9	7.94						11/1/2011 2:36 PM

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011				58	8.4						
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011				133.9	7.34						
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011				87.8	8.13						
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011				241.8	7.57						
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011				147	8.8						
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011				115	8.62						
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011				125.9	8.53						
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011				71.3	8.1						
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011				218.9	7.95						

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	TSS (mg/L)	Turbidity (ntu)	TPH	Fecal Coliform (cfu/100ml)	Total Coliform (cfu/100ml)	Aluminum (mg/L)	Aluminum (SAC 942) (mg/L)	Aluminum (SAC 160) (mg/L)
Primary Maximum Contaminant Levels	a											0	0			
Secondary Maximum Contaminant Levels	b													0.05-0.2	0.05-0.2	0.05-0.2
Recommended Action Levels	c															
			Well				CABOT	5/13/2008	<5.0							
			Well				CABOT	11/05/2008	<2.0			<1	<1	0.071		
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009								
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009	<2.0		<0.100			0.106		
			Well				DEP	5/13/2010						13.7		
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	3/13/2010	34	45	<0.10			2.51		
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010	18	30	<0.11	<1	<1	1.52		
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010								
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010								
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010	14.8	16.8	<0.11	<1	1	1.42		
			Well			DEP	5/27/2010							0.334		
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010	8.4	14	<0.11	<1	<1	0.448		
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010	6	6	<0.11	1	<1	0.142		
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010	6	9	<0.10	<1	<1	0.137		
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010	2.4	2.85	<0.10	54	54	<0.100		
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010	<2.0	3	<0.10	<1	<1	<0.100		
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010	<2.0	2	<0.11	<1	<1	<0.100		
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010	<2.0	2	<0.10	<1	<1	<0.100		
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010	2	2	<0.11	NTIC	NTIC	<0.100		
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010	<2.0		<0.10	<1	400	<0.100		
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010	<2.0	3	<0.10	<1	62	<0.100		
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010	<2.0	1	<10.0	<1	12	<0.100		
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010	<2.0	<1.0	<0.10	<1	40	<0.100		
AFTER FILTER			Well			Post-Treatment	CABOT	08/06/2010	<2.0	<1	<0.10	<1 cfu/100 ml	<1 cfu/100 ml			
			Well			DEP	8/11/2010							<0.200		
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010								
			Well			DEP	8/18/2010							0.031		
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010	<2.0	3	<0.10	<1	<1	<0.100		
			Well			DEP	8/24/2010		<1	<0.10				<0.2		
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010	<2.0	<1	<0.10	<1	<1	<0.100		
			Well			DEP	8/31/2010							<0.200		
			Well			DEP	9/2/2010							<0.200		
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/2/2010	<2.0	1	<0.10	<1	<1	0.1		
			Well			DEP	9/9/2010							<0.200		
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010	<2.0	1	<0.10	<1	<1	0.046		
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010						<0.200		
			Well			DEP	9/30/2010			4.67					<0.200	0.111
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010						<0.200		
			Well			DEP	10/14/2010							<0.200		
			Well			DEP	10/28/2010							<0.200		
			Well			DEP	11/2/2010							<0.200		
			Well			DEP	11/9/2010							<0.200		
			Well			DEP	11/22/2010							<0.200		
			Well			DEP	12/2/2010							<0.200		
			Well			DEP	12/7/2010							<0.200		
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010								
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011								
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011								
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011								
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/17/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011								
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011								11/1/2011 2:26 PM

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011								
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011								
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011								
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011								
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011								
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011								

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	Antimony (mg/L)	Arsenic (mg/L)	Barium (mg/L)	Barium (SAC 942) (mg/L)	Barium (SAC 161) (mg/L)	Beryllium (SAC 161) (mg/L)	Calcium (mg/L)	Chromium (mg/L)
Primary Maximum Contaminant Levels	a								0.006	0.01	2	2	2	0.004		0.1
Secondary Maximum Contaminant Levels	b															
Recommended Action Levels	c															
			Well				CABOT	5/13/2008								
			Well				CABOT	11/05/2008			0.27					
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009								
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009			0.199					
			Well				DEP	5/13/2010							35.59	
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	3/13/2010			0.329					
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010			0.363					
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010								
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010								
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010			0.51					
			Well			DEP	5/27/2010			0.435					24.4	
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010			0.403					
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010			0.401					
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010			0.388					
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010			0.427					
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010			0.434					
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010			0.437					
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010			0.422					
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010			0.436					
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010			0.448					
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010			0.329					
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010			0.348					
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010			0.398					
AFTER FILTER			Well			Post-Treatment	CABOT	08/06/2010								
			Well			DEP	8/11/2010			0.373					26.8	
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010								
			Well			DEP	8/18/2010			0.407					29.9	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010			0.376					
			Well			DEP	8/24/2010			0.409						
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010			0.382					
			Well			DEP	8/31/2010			0.112					34.2	
			Well			DEP	9/2/2010			0.377					27.6	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/2/2010			0.357					
			Well			DEP	9/9/2010			0.404						
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010			0.405					
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010								
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well			DEP	9/30/2010	<0.002	0.0033		0.342		0.398	<0.001	22.7	<0.004
			Well			CABOT	10/12/2010									
			Well			DEP	10/14/2010			0.318					17.7	
			Well			DEP	10/28/2010			0.324					19.8	
			Well			DEP	11/2/2010			0.234					13.8	
			Well			DEP	11/9/2010			0.247					12.8	
			Well			DEP	11/22/2010			0.265					13	
			Well			DEP	12/2/2010			0.297					19.7	
			Well			DEP	12/7/2010			0.352					24.3	
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010								
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011								
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011								
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011								
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/11/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011								
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011								11/1/2011 2:26 PM

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011								
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011								
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011								
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011								
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011								
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011								

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	Iron (mg/L)	Iron (SAC 942) (mg/L)	Iron (SAC 160) (mg/L)	Magnesium (mg/L)	Magnesium (SAC 942) (mg/L)	Magnesium (SAC 160) (mg/L)	Manganesa (mg/L)
Primary Maximum Contaminant Levels	a														
Secondary Maximum Contaminant Levels	b								0.3	0.3	0.3				0.05
Recommended Action Levels	c														
			Well				CABOT	5/13/2008	<0.050			2.27			
			Well				CABOT	11/05/2008	0.058			1.3			<0.005
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009							
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009	0.036			<1.000			0.041
			Well				DEP	5/13/2010	16.06						0.374
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	5/13/2010	2.22			<1.000			0.075
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010	1.5			2.27			0.117
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010							
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010							
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010	1.42			4.71			0.259
			Well				DEP	5/27/2010	0.299			4.111			0.047
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010	0.34			4.8			0.098
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010	0.243			5.13			0.074
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010	0.18			4.99			0.047
			Well												
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010	0.097			4.92			0.134
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010	0.158			5.06			0.237
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010	0.143			4.96			0.14
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010	0.143			5.1			0.068
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010	0.493			5.14			0.188
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010	0.136			5.04			0.029
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010	0.05			5.09			<0.025
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010	0.065			4.88			0.062
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010	<0.050			4.95			0.025
			Well				CABOT	08/06/2010							
			Well				DEP	8/11/2010	0.064			5.343			0.038
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010							
			Well				DEP	8/18/2010	0.195			5.043			0.059
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010	<0.050			5.12			<0.025
			Well				DEP	8/24/2010	0.065			5.199			0.054
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010	<0.050			5.07			0.038
			Well				DEP	8/31/2010	<0.020			8.796			<0.010
			Well				DEP	9/2/2010	0.034			5.365			0.056
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/2/2010	<0.050			5.04			<0.025
			Well				DEP	9/9/2010	0.144			5.188			0.067
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010	<0.050			4.48			<0.025
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010							
			Well				DEP	9/30/2010		0.127	0.316		3.682	3.751	
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010							
			Well				DEP	10/14/2010	0.032			2.835			0.016
			Well				DEP	10/28/2010	0.03			3.43			0.016
			Well				DEP	11/2/2010	0.056			2.168			0.012
			Well				DEP	11/9/2010	0.031			2.092			<0.010
			Well				DEP	11/22/2010	0.08			2.162			<0.010
			Well				DEP	12/2/2010	0.024			3.086			<0.010
			Well				DEP	12/7/2010	<0.020			4.055			<0.010
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010							
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011							
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011							
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011							
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/17/2011							
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011							
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011							
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011							
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011							11/1/2011 2:26 PM

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011							
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011							
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011							
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011							
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011							
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011							
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011							
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011							
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011							

Notes:

a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)

b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.

c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	Manganese (SAC 942) (mg/L)	Manganese (SAC 160) (mg/L)	Mercury (mg/L)	Nickel (mg/L)	Potassium (mg/L)	Selenium (mg/L)	Sodium (SAC 942) (mg/L)
Primary Maximum Contaminant Levels	a										0.002			0.05	
Secondary Maximum Contaminant Levels	b								0.05	0.05					
Recommended Action Levels	c														
			Well				CABOT	5/13/2008							
			Well				CABOT	11/05/2008							
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009							
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009							
			Well				DEP	5/13/2010					4.433		36.87
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	5/13/2010							
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010							
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010							
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010							
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010							
			Well				DEP	5/27/2010					1.849		23.6
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010							
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010							
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010							
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010							
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010							
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010							
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010							
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010							
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010							
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010							
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010							
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010							
			Well			Post-Treatment	CABOT	08/06/2010							
			Well				DEP	8/11/2010					1.606		11.6
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010							
			Well				DEP	8/18/2010					1.641		13.3
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010							
			Well				DEP	8/24/2010					1.76		13.6
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010							
			Well				DEP	8/31/2010					1.536		12
			Well				DEP	9/2/2010					1.708		12.7
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/2/2010							
			Well				DEP	9/9/2010					1.753		13.1
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010							
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010							
			Well				DEP	9/30/2010	0.055	0.065	<0.0002	<0.05	1.647	<0.007	29.5
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010							
			Well				DEP	10/14/2010					1.636		42
			Well				DEP	10/28/2010					1.621		30.7
			Well				DEP	11/2/2010					1.496		51.2
			Well				DEP	11/9/2010					1.695		65.8
			Well				DEP	11/22/2010					1.547		51.9
			Well				DEP	12/2/2010					1.629		37.7
			Well				DEP	12/7/2010					1.67		21.5
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010							
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011							
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011							
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011							
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/17/2011							
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011							
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011							
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011							
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011							11/1/2011

2:26 PM

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011							
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011							
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011							
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011							
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011							
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011							
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011							
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011							
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011							

Notes:

a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)

b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.

c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	Sodium (SAC 160) (mg/L)	Strontium (mg/L)	Thallium (mg/L)	Zinc (mg/L)	VOADW	VOADW BLANK	SVWW	BIS (2-Ethylhexyl) phthalate (SVDW) (mg/L)
Primary Maximum Contaminant Levels	a										0.002					
Secondary Maximum Contaminant Levels	b											5				
Recommended Action Levels	c															
			Well				CABOT	5/13/2008								
			Well				CABOT	11/05/2008		0.55						
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009								
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009		0.396						
			Well				DEP	5/13/2010		0.913						
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	5/13/2010		0.263						
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010		0.908						
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010								
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010								
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010		1.26						
			Well				DEP	5/21/2010		1.11						
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010		1.18						
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010		1.12						
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010		1.09						
			Well													
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010		1.1						
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010		1.13						
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010		1.13						
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010		1.12						
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010		1.09						
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010		1.12						
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010		1.03						
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010		1.03						
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010		1.08						
AFTER FILTER			Well			Post-Treatment	CABOT	08/06/2010								
			Well				DEP	8/11/2010								
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010								
			Well				DEP	8/18/2010		1.153						
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010		1.11						
			Well				DEP	8/24/2010		1.189						
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010		1.1						
			Well				DEP	8/31/2010		1.08						
			Well				DEP	9/2/2010		1.16						
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/2/2010		1.06						
			Well				DEP	9/9/2010		1.22						
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010		1.08						
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010								
			Well				DEP	9/30/2010	30	0.959	<0.002	0.03	NON DETECT	NON DETECT	NON DETECT	0.00014
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010								
			Well				DEP	10/14/2010		0.844						
			Well				DEP	10/28/2010		0.985						
			Well				DEP	11/2/2010		0.958						
			Well				DEP	11/9/2010		0.695						
			Well				DEP	11/22/2010		0.725						
			Well				DEP	12/2/2010		0.972						
			Well				DEP	12/7/2010		1.142						
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010								
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011								
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011								
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011								
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/17/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011								
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011								
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011								11/1/2011 2:36 PM

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011								
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011								
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011								
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011								
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011								
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011								
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011								

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	EDB	EDB-BLANK	Ethane (ug/L)	Ethene (ug/L)	iso-Butane (ug/L)	Methane (ug/L)	n-Butane (ug/L)	Propane (ug/L)
Primary Maximum Contaminant Levels	a															
Secondary Maximum Contaminant Levels	b															
Recommended Action Levels	c													25,000		
			Well				CABOT	5/13/2008								
			Well				CABOT	11/05/2008								
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009						3610		
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009								
			Well				DEP	5/13/2010			0.69	CANCELLED		1180		CANCELLED
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	3/13/2010			0.35		<0.050	2000	<0.050	<0.050
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010			NON DETECT		<0.050	1500	<0.050	<0.050
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010			NON DETECT					
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010			NON DETECT					
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010			<0.025		<0.050	13	<0.050	<0.050
			Well				DEP	5/21/2010			NON DETECT	NON DETECT		510		NON DETECT
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010			<0.025		<0.050	43	<0.050	<0.050
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	5/3/2010			<0.025		<0.050	1.6	0.067	<0.050
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010			<0.025		<0.050	2	<0.050	<0.050
			Well				CABOT	6/10/2010			<0.025		<0.050	3.7	<0.050	<0.050
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well			Post-Treatment	CABOT	6/14/2010			<0.025		<0.050	29	<0.050	<0.050
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010			<0.025		<0.050	7.1	<0.050	<0.050
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/24/2010			<0.025		<0.050	1	<0.050	<0.050
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	7/1/2010			<0.025		<0.050	9.7	<0.050	<0.050
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010			<0.025		<0.050	2.2	<0.050	<0.050
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/15/2010			<0.025		<0.050	0.49	<0.050	<0.050
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/22/2010			0.008		<0.050	0.81	<0.050	<0.050
FILTER OFF OF WELL		FILTER OFF OF WELL	Well			Post-Treatment	CABOT	7/29/2010			0.013		<0.050	0.51	<0.050	0.014
AFTER FILTER			Well			Post-Treatment	CABOT	08/06/2010			0.014		<0.050	0.71	<0.050	<0.050
			Well			DEP	8/11/2010				NON DETECT			NON DETECT		NON DETECT
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010								
			Well				DEP	8/18/2010			NON DETECT			11.4		
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010			0.014		<0.050	0.51	<0.050	0.012
			Well				DEP	8/24/2010			NON DETECT			19.6		NON DETECT
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010			0.024		<0.050	0.64	<0.050	0.014
			Well				DEP	8/31/2010			NON DETECT					
			Well				DEP	9/2/2010			0.024	NON DETECT		13.2		NON DETECT
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/3/2010			NON DETECT		0.036	0.66	0.011	0.021
			Well				DEP	9/9/2010			0.03	NON DETECT		18.3		NON DETECT
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010					<0.050	6.7	<0.050	<0.050
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010								NON DETECT
			Well			DEP	9/30/2010		NON DETECT	NON DETECT	NON DETECT	NON DETECT		49.9		NON DETECT
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010								NON DETECT
			Well				DEP	10/14/2010			NON DETECT	NON DETECT		218		NON DETECT
			Well				DEP	10/28/2010			NON DETECT	NON DETECT		580		NON DETECT
			Well				DEP	11/2/2010			NON DETECT	NON DETECT		1750		NON DETECT
			Well				DEP	11/9/2010			NON DETECT	NON DETECT		2130		NON DETECT
			Well				DEP	11/22/2010			NON DETECT	NON DETECT		1080		NON DETECT
			Well				DEP	12/2/2010			NON DETECT	NON DETECT		1040		NON DETECT
			Well				DEP	12/7/2010			NON DETECT	NON DETECT		42.9		NON DETECT
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010			0.02		0.06	4.8	0.06	0.06
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011			0.15		0.06	480	0.06	0.008
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011			0.14		0.06	430	0.06	0.06
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011			0.18		0.06	570	0.06	0.06
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/11/2011			0.2		0.06	690	0.06	0.06
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011			0.048		0.06	93	0.06	0.06
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011			0.23		0.06	780	0.06	0.06
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011			0.2		0.06	0.1	0.06	0.06
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011			150		0.06	510	0.06	0.06

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011				0.21			0.05	770	0.05	0.05
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011				0.22			0.05	940	0.05	0.05
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011				0.37			<0.050	1400	<0.050	<0.050
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011				0.4			<0.500	1700	<0.050	<0.050
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011				.97			<0.005	3500	<0.050	0.053
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011				0.14			<0.050	560	<0.050	0.17
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011				0.13			<0.050	570	<0.050	<0.050
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011				0.076			<0.050	240	<0.050	<0.050
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011				<0.025			<0.050	40	<0.050	<0.050

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

		Sample Location	Sample Medium	Latitude	Longitude	Treatment Collection	Source	Sample Date	Sample Sheet Comments
Primary Maximum Contaminant Levels	a								
Secondary Maximum Contaminant Levels	b								
Recommended Action Levels	c								
			Well				CABOT	5/13/2008	
			Well				CABOT	11/05/2008	
KITCHEN SINK		KITCHEN SINK	Well				DEP	2/23/2009	
PRESSURE TANK - AFTER FILTER		PRESSURE TANK - AFTER FILTER	Well			Post-Treatment	CABOT	10/30/2009	
			Well				DEP	5/13/2010	
HYDRANT FROM WELL		HYDRANT FROM WELL	Well			Pre-Treatment	CABOT	5/13/2010	DIRTY WATER PH 8.69
OUTSIDE SPIGOT		OUTSIDE SPIGOT	Well			Pre-Treatment	CABOT	5/15/2010	
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/16/2010	PH ONLY ANALYZED PER BRENT BRELJE AT SLR
PRESSURE TANK AT WELL HEAD		PRESSURE TANK AT WELL HEAD	Well			Pre-Treatment	CABOT	5/18/2010	PH ONLY ANALYZED PER BRENT BRELJE AT SLR
PRESSURE TANK SPIGOT AT WELL HEAD		PRESSURE TANK SPIGOT AT WELL HEAD	Well			Pre-Treatment	CABOT	5/20/2010	
			Well				DEP	5/21/2010	
PRESSURE TANK NEAR WELL HEAD		PRESSURE TANK NEAR WELL HEAD	Well			Pre-Treatment	CABOT	5/27/2010	
PRESSURE TANK BEFORE FILTER		PRESSURE TANK BEFORE FILTER	Well			Pre-Treatment	CABOT	6/3/2010	
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/3/2010	
OUTSIDE HYDRANT WITH FILTER		OUTSIDE HYDRANT WITH FILTER	Well				CABOT	6/10/2010	FILTER WAS ATTACHED TO THE SPIGOT/HYDRANT. AS SOON AS WATER FLOWED IT FOAMED LIKE SOAP EXCESSIVELY.
PRESSURE TANK AFTER FILTER		PRESSURE TANK AFTER FILTER	Well			Post-Treatment	CABOT	6/14/2010	
OUTSIDE HYDRANT AFTER FILTER		OUTSIDE HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	6/17/2010	
AFTER FILTER AT HYDRANT		AFTER FILTER AT HYDRANT	Well			Post-Treatment	CABOT	6/24/2010	SOME FOAMING
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/1/2010	
HYDRANT AFTER FILTER		HYDRANT AFTER FILTER	Well			Post-Treatment	CABOT	7/8/2010	
SPIGOT ON FILTER OFF OF WELL		SPIGOT ON FILTER OFF OF WELL	Well				CABOT	7/15/2010	
FILTER OFF OF WELL		FILTER OFF OF WELL	Well				CABOT	7/22/2010	
AFTER FILTER			Well			Post-Treatment	CABOT	7/29/2010	
AFTER FILTER			Well			Post-Treatment	CABOT	08/06/2010	
			Well				DEP	8/11/2010	
AT WELL HYDRANT- AFTER FILTER		AT WELL HYDRANT- AFTER FILTER	Well			Post-Treatment	CABOT	8/12/2010	
			Well				DEP	8/18/2010	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	8/19/2010	
			Well				DEP	8/24/2010	
AFTER FILTER			Well			Post-Treatment	CABOT	8/26/2010	
			Well				DEP	8/31/2010	
			Well				DEP	9/2/2010	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	9/2/2010	
			Well				DEP	9/9/2010	
SPIGOT OFF OF FILTER		SPIGOT OFF OF FILTER	Well			Post-Treatment	CABOT	09/09/2010	
KITCHEN FAUCET		KITCHEN FAUCET	Well			Post-Treatment	CABOT	09/23/2010	CHLORINE WAS ADDED TO THE WELL ON 09-20-10
			Well				DEP	9/30/2010	
BASEMENT AT PRESSURE TANK		BASEMENT AT PRESSURE TANK	Well				CABOT	10/12/2010	
			Well				DEP	10/14/2010	
			Well				DEP	10/28/2010	
			Well				DEP	11/2/2010	
			Well				DEP	11/9/2010	
			Well				DEP	11/22/2010	
			Well				DEP	12/2/2010	
			Well				DEP	12/7/2010	
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	12/21/2010	
WELL HYDRANT		WELL HYDRANT	Well			Pre-Treatment	CABOT	1/7/2011	
OUTSIDE HYDRANT OFF TOP OF WELL		OUTSIDE HYDRANT OFF TOP OF WELL	Well			Pre-Treatment	CABOT	1/20/2011	
OUTSIDE HYDRANT OFF OF WELL		OUTSIDE HYDRANT OFF OF WELL	Well			Pre-Treatment	CABOT	2/3/2011	
AT WELL HYDRANT		AT WELL HYDRANT	Well			Pre-Treatment	CABOT	2/17/2011	
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/3/2011	
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	3/17/2011	
OUTSIDE HYDRANT ON TOP OF WELL		OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	4/19/2011	
OUTSIDE HYDRANT		OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	4/26/2011	

11/1/2011 2:26 PM

DIM0192145

DIM0192161

OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/10/2011	
OUTSIDE HYDRANT ON TOP OF WELL			OUTSIDE HYDRANT ON TOP OF WELL	Well			Pre-Treatment	CABOT	5/24/2011	
OUTSIDE HYDRANT			OUTSIDE HYDRANT	Well			Pre-Treatment	CABOT	6/7/2011	
WELL 1				Well			Pre-Treatment	CABOT	7/6/2011	
WELL 1				Well			Pre-Treatment	CABOT	7/20/2011	
WELL 1				Well			Pre-Treatment	CABOT	8/3/2011	
WELL 1				Well			Pre-Treatment	CABOT	8/17/2011	
WELL 1				Well			Pre-Treatment	CABOT	8/31/2011	
WELL 1				Well			Pre-Treatment	CABOT	9/15/2011	

Notes:

a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)

b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.

c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)